

General Environmental Incident Summary

Incident: 5209 **Date/Time Notice:** 8/26/2016 10:45 **DEM Incident No:**
Responsible Party: Dakota gasification Company
Date Incident: 8/26/2016 **Time Incident:** 10:45 **Duration:** 1 hours
County: Mercer **Twp:** 145 **Rng:** 87 **Sec:** 18 **Qtr:**
Lat: 47.37790 **Long:** -101.82240 **Method:** Interpolation from map
Location Description: DGC - closed landfill Permit No. 0100

Submitted By: Jacob Scott **Affiliation:** DGC
Address: 420 County Rd 26
City: Beulah **State:** ND **Zip:** 58523

Received By:

Contact Person: Jacob Scott
420 County Rd 26
Beulah, ND 58523

Distance Nearest Occupied Building: 0.5 Miles **Release Contained:** Yes

Type of Incident: Leachate spill on ground

Description of Released Contaminant: Landfill Leachate (contains arsenic and selenium)

Volume Spilled: **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Pipe loading tank was discovered not to be in tank

Risk Evaluation:

NONE

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

impacted soil is located above closed landfill. Soil will be removed and replaced. Area will be re-vegetated.

Action Taken or Planned:

Pumps shut down. contaminated vegetation and soil will be removed. Soil will be replaced and area reseeded

Wastes Disposal Location: Active landfill permit no. 0109

Agencies Involved:

Updates

Date: 8/26/2016 ***Status:*** Reviewed - Assigned to NDDoH Division

Author: O'Gorman, Brian

Updated Volume:

Notes:

Landfill is permitted by Division of Waste Management. Report forwarded to the division.